

# End of Life (EOL) Notice

17<sup>th</sup> January 2023

## To our Valued Customers:

Laird Connectivity is officially announcing the End of Life (EOL) effective from this notice for the following part numbers from the 60 Series SOM product family and any potential replacements recommended by Laird Connectivity are outlined below:

Discontinued	Description	Potential replacements
453-00003	60 Series SOM - 1Gb LPDDR1 & 2Gb NAND flash – <i>No Programmed Software</i>	453-00004, 453-00137, 453-00138
453-00038, 453-00074, 453-00129	60 Series SOM - 1Gb LPDDR1 & 2Gb NAND flash – <i>Custom Top Level Part Number</i>	NA

Laird Connectivity has allocated each current production customer a specific number of the base 453-00003 parts to allow for a multi-year timeline to transition to the new pin and footprint compatible parts.

Please contact Laird Connectivity Sales to review the number of parts allocated to your project and to discuss the options for transitioning to the pin and footprint compatible replacement part numbers.

The additional table on page 2 shows the affected top level custom part numbers where the standard base hardware part number (453-00003) is programmed by Laird Connectivity with a custom software image. Each custom software image has a unique lower level part number.

The top level custom part numbers shown below are generated to uniquely identify the combination of base hardware part number and the customer specific programmed software.

Top Level Custom Part Number	Description	Potential hardware part number replacements	Potential software part number replacements
453-00073, 453-00092, 453-00106, 453-00121, 453-00123, 453-00124 453-00132, 453-00149, 453-00190	60 Series SOM - 1Gb LPDDR1 & 2Gb NAND flash – <i>Custom Programmed Software</i>	453-00004, 453-00137, 453-00138	TBC *

\* Once a new base hardware part number is selected and a corresponding updated software image is generated, Laird Connectivity will provide a new top level custom part number.

We apologize for any inconvenience that this may cause. Please contact your usual sales representative as soon as possible to discuss.

Sincerely,



**Dan Kephart**  
Senior Product Manager  
Laird Connectivity