

Product Change Notification (PCN)

PCN #: 4L-2025

Date: April 21, 2025

1 Products Affected

Ezurio Part Number	Description
453-00003	Module, SU60-SOMC, 1Gb RAM
453-00004	Module, SU60-SOMC, 2Gb RAM
453-00137	Module, SU60-SOMC, 1Gb LPDDR2
453-00138	Module, SU60-SOMC, 2Gb LPDDR2
453-00032	Module, Custom SU60-SOMC, 2Gb RAM with Custom Software
453-00073	Module, SU60-SOMC, 1Gb RAM with Custom Software
453-00092	Module, SU60-SOMC, 1Gb RAM with Custom Software
453-00106	Module, SU60-SOMC, 1Gb RAM with Custom Software
453-00121	Module, SU60-SOMC, 1Gb RAM with Custom Software
453-00123	Module, SU60-SOMC, 1Gb RAM with Custom Software
453-00124	Module, SU60-SOMC, 1Gb RAM with Custom Software
453-00132	Module, SU60-SOMC, 1Gb RAM with Custom Software
453-00133	Module, SU60-SOMC, 2Gb RAM with Custom Software
453-00149	Module, SU60-SOMC, 1Gb RAM with Custom Software
453-00182	Module, SU60-SOMC, 2Gb RAM with Custom Software
453-00190	Module, SU60-SOMC, 1Gb RAM with Custom Software
453-00227	Module, SU60-SOMC, 2Gb LPDDR2 with Custom Software
453-00233	Module, SU60-SOMC, 2Gb LPDDR2 with Custom Software
453-00369	Module, SU60-SOMC, 2Gb LPDDR2 with Custom Software

2 Description of Changes

All changes have been applied to the part numbers listed above:

- Change the country of origin from Taiwan to Vietnam.
- Remove the PCB bottom silkscreen of non-LPDDR2 PNs

3 Reason for Change

- Expansion of manufacturing footprint, outside of Taiwan.
- Remove the PCB bottom side silkscreen from non-LPDDR2 PNs to prevent PCB unevenness from causing SMT issues.

4 Anticipated Impact of the Change

There is no form, fit or functional change caused by this PCN.

5 Method of Identifying the Changed Product

5.1 Update Labels

- Product label adds a symbol “V” to identify Made in Vietnam

Before (453-00137 in the exemplary photo)



After (453-00137 in the exemplary photo)



- Antistatic bag label and box label adds a symbol “V” to identify Made in Vietnam

Before (453-00137 in the exemplary photo)



After (453-00137 in the exemplary photo)



- Carton label changes COO from Made in China to Made in Vietnam

After (453-00137 in the exemplary photo)


After (453-00137 in the exemplary photo)




5.2 PCB Silkscreen

- 453-00003/453-00004/453-00032/453-00063/453-00092/453-00106/453-00121/453-00123/453-00124/453-00132/453-00133/453-00149/453-00182/453-00190, remove the PCB bottom side silkscreen and move it to the top side, as indicated by the red-marked area. Removal of silkscreen on PCB bottom will be a running change after consuming existing PCB inventory.

Before



After



6 Factory Effectivity Date

These changes will be implemented into manufacturing starting from Date Codes, as outlined below for each product variant. The date code is shown on each label, as format SSYYWWDD.

SS = Supplier code

YY = last two numbers of the year (ex: 18=2018, 19=2019)

WW = Week of the year

D = day of the week (ex: Sun=1, Mon=2, Tue=3, Wed=4, Thu=5, Fri=6, Sat=7)

Ezurio Part Number	Factory Effectivity – Date Codes
453-00003	0925281
453-00004	0925281
453-00137	0925281
453-00138	0925281
453-00032	0925281
453-00073	0925281
453-00092	0925281
453-00106	0925281
453-00121	0925281
453-00123	0925281
453-00124	0925281
453-00132	0925281
453-00133	0925281
453-00149	0925281
453-00182	0925281
453-00190	0925281
453-00227	0925281
453-00233	0925281
453-00369	0925281

7 Contact Information

Headquarters Ezurio
50 S Main St., Suite 1100
Akron, OH 44308 USA
Tel: 1(330) 434-7929
Fax: 1(330) 434-7931

Website www.ezurio.com

Sales / Support Contact <https://www.ezurio.com/contact>



Product Change Notices (PCNs) will be distributed at the discretion Ezurio. Occasionally, Ezurio may adjust product revision levels for internal tracking purposes only, and customers may not receive formal notifications associated with those revision changes.