

Product Change Notification (PCN)

PCN #: 6N-2025

Date: June 26, 2025

1 Products Affected

Ezurio Part Number	Description
453-00139R	LoRaWAN Module, RM1262, SX1262, MHF4, Tape and Reel
453-00139C	LoRaWAN Module, RM1262, SX1262, MHF4, Cut Tape
453-00139-K1	Development Kit, RM1262, SX1262, MHF4
453-00140R	LoRaWAN Module, RM1261, SX1261, MHF4, Tape and Reel
453-00140C	LoRaWAN Module, RM1261, SX1261, MHF4, Cut Tape
453-00140-K1	Development Kit, RM1261, SX1261, MHF4

2 Description of Changes

All changes have been applied to the part numbers listed above:

- Replace all Laird Connectivity company information and branding with Ezurio company information and branding, including:-
 - On product labels
 - Packaging labels inclusive of any reel, anti-static bag, box and carton labels.
 - PCB silkscreen

3 Reason for Change

The changes are required to align with the new company information and branding – Ezurio.

4 Anticipated Impact of the Change





There is no form, fit or functional change caused by this PCN, only cosmetic branding changes leading to a revision update.

5 Method of Identifying the Changed Product

5.1 Update Labels

453-00139R/453-00139C/453-00139-K1/453-00140R/453-00140C/453-00140-K1

- On the device label, replace logo from Laird Connectivity to Ezurio
- On the device label, update product revision from R1 to R2

Before	After
 <p>Model: RM1262 R1 P/N: 453-00139 FCC ID: SQG-RM1262 IC: 3147A-RM1262 DC: SSYYWWD Laird Connectivity R-NZ</p>	 <p>Model: RM1262 R2 P/N: 453-00139 FCC ID: SQG-RM1262 IC: 3147A-RM1262 DC: SSYYWWD Ezurio R-NZ</p>
 <p>Model: RM1261 R1 P/N: 453-00140 DC: SSYYWWD Laird Connectivity UK CA CE R 201-220688</p>	 <p>Model: RM1261 R2 P/N: 453-00140 DC: SSYYWWD Ezurio UK CA CE R 201-220688</p>













453-00139R/453-00139C/453-00140R/453-00140C

- On the reel, bag, and box labels
 - o Update product revision from R1 to R2 on the product identifier label. RX in the AFTER example photo, X being a variable, subject to change based on the hardware revision.
 - o Replace Laird Connectivity logo with Ezurio logo on the product identifier label

Before	After
<div> M/N:RM1262 R1 P/N:453-00139R D/C:SSYYWWD Q'TY:1000PCS BOX_ID:BXXXXXXYMDXXXXXX  </div> <div>   R-NZ </div>	<div> M/N:RM1262 RX P/N:453-00139R D/C:SSYYWWD Q'TY:1000PCS BOX_ID:BXXXXXXYMDXXXXXX  </div> <div>   R-NZ </div>
<div> M/N:RM1261 R1 P/N:453-00140R D/C:SSYYWWD Q'TY:1000PCS BOX_ID:BXXXXXXYMDXXXXXX  </div> <div>   CE UK CA </div>	<div> M/N:RM1261 RX P/N:453-00140R D/C:SSYYWWD Q'TY:1000PCS BOX_ID:BXXXXXXYMDXXXXXX  </div> <div>   CE UK CA </div>


453-00139R/453-00139C/453-00140R/453-00140C

- On the shipping carton label,
 - o Update product revision from Revision 1 to 2. Revision X in the AFTER-example photo, X being a variable, subject to change based on the hardware revision
 - o Replace Laird Connectivity logo with Ezurio logo
 - o Replace Laird Connectivity company name with Ezurio company name

Before	After
 <p>CONNECTIVITY</p> <p>P/N:453-00139R Revision:1 Description:LoRa Module,RM1262, SX1262,MHF4,Tape*and*Reel Quantity:XXXX Date*Code:SSYYWWD Country*of*Origin:VN Laird*Connectivity 50*S.*Main*St.*Ste.*1100 Akron,*OH*44308</p>  <p>PO:XXXXXXX</p>  <p>www.lairdconnect.com</p>	  <p>P/N: 453-00139R Revision: X Description:</p> <p>Quantity: XXXX Date Code: SSYYWWD Country of Origin: XX</p> <p>Ezurio 50 S. Main St. Ste. 1100 Akron, OH 44308</p>  <p>www.ezurio.com</p>
 <p>CONNECTIVITY</p> <p>P/N:453-00140R Revision:1 Description:LoRa Module,RM1261, SX1261,MHF4,Tape*and*Reel Quantity:XXXX Date*Code:SSYYWWD Country*of*Origin:VN Laird*Connectivity 50*S.*Main*St.*Ste.*1100 Akron,*OH*44308</p>  <p>PO:XXXXXXX</p>  <p>www.lairdconnect.com</p>	  <p>P/N: 453-00140R Revision: X Description:</p> <p>Quantity: XXXX Date Code: SSYYWWD Country of Origin: XX</p> <p>Ezurio 50 S. Main St. Ste. 1100 Akron, OH 44308</p>  <p>www.ezurio.com</p>



453-00139-K1/453-00140-K1

- PCB logo to replace logo from Laird Connectivity to Ezurio



453-00139-K1/453-00140-K1

- On the kit box, update the base label from Laird Connectivity artwork style to Ezurio artwork style.
- On the kit box, update the revision on the content label from Rev 1 to Rev 2

Before	After
 <p>RM126x Development Kit</p> <p>To get started with the RM126x Series, visit: lairdconnect.com/rm126x-series</p> <p>Laird CONNECTIVITY</p>	 <p>RM126x Development Kit</p> <p>To get started visit: www.ezurio.com/rm126x-series</p> <p>ezurio</p>
<div data-bbox="110 993 406 1098"> <p>453-00139-K1</p> <p>1. 1 x RM1262 Development Board</p> <p>2. 1 x Micro USB Cable</p> <p>3. 1 x I-FlexPIFA, 915MHz Antenna (Part#EFG0020A3S-15MH4L)</p> </div> <div data-bbox="438 993 730 1098"> <p>Part Number: 453-00139-K1</p> <p>Model Name: RM1262 Rev 1</p> <p>Description: Development Kit, RM1262, SX1262, MHF4</p> </div>	<div data-bbox="808 993 1104 1098"> <p>453-00139-K1</p> <p>1. 1 x RM1262 Development Board</p> <p>2. 1 x Micro USB Cable</p> <p>3. 1 x I-FlexPIFA, 915MHz Antenna (Part#EFG0020A3S-15MH4L)</p> </div> <div data-bbox="1133 993 1429 1098"> <p>Part Number: 453-00139-K1</p> <p>Model Name: RM1262 Rev 2</p> <p>Description: Development Kit, RM1262, SX1262, MHF4</p> </div>
<div data-bbox="110 1203 406 1308"> <p>453-00140-K1</p> <p>1. 1 x RM1261 Development Board</p> <p>2. 1 x Micro USB Cable</p> <p>3. 1 x I-FlexPIFA, 915MHz Antenna (Part#EFG0020A3S-15MH4L)</p> <p>4. 1 x I-FlexPIFA, 868MHz Antenna (Part#EFG0055A3S-15MH4L)</p> </div> <div data-bbox="438 1203 730 1308"> <p>Part Number: 453-00140-K1</p> <p>Model Name: RM1261 Rev 1</p> <p>Description: Development Kit, RM1261, SX1261, MHF4</p> </div>	<div data-bbox="808 1203 1104 1308"> <p>453-00140-K1</p> <p>1. 1 x RM1261 Development Board</p> <p>2. 1 x Micro USB Cable</p> <p>3. 1 x I-FlexPIFA, 915MHz Antenna (Part#EFG0020A3S-15MH4L)</p> <p>4. 1 x I-FlexPIFA, 868MHz Antenna (Part#EFG0055A3S-15MH4L)</p> </div> <div data-bbox="1133 1203 1429 1308"> <p>Part Number: 453-00140-K1</p> <p>Model Name: RM1261 Rev 2</p> <p>Description: Development Kit, RM1261, SX1261, MHF4</p> </div>

453-00139-K1/453-00140-K1

- On the shipping carton label,
 - Update product revision from Revision 1 to 2. Revision R in the AFTER example photo, R being a variable, subject to change based on the hardware revision.
 - Replace Laird Connectivity logo with Ezurio logo
 - Replace Laird Connectivity company name with Ezurio company name

Before	After
 <p> CONNECTIVITY P/N: Part Number Revision: R Description: Product Description: Line 2 if Needed Quantity: Date Code: 0519266 Country of Origin: TW Laird Connectivity 50 S. Main St. Ste. 1100 Akron, OH 44308 </p> <p>PO: PO #</p>  <p>www.lairdconnect.com</p>	 <p> P/N: Part Number Revision: R Description: Product Description: Line 2 if Needed Quantity: #### Date Code: SSYYWWD Country of Origin: XX Ezurio 50 S. Main St. Ste. 1100 Akron, OH 44308 </p> <p>PO: J#####</p>  <p>www.ezurio.com</p>

6 Factory Effectivity Date

6.1 Factory Effectivity Date

These changes will be implemented into manufacturing starting from Date Codes, as outlined below for each product variant. The date code is shown on each label, as format SSYYWWDD.

SS = Supplier code

YY = last two numbers of the year (ex: 18=2018, 19=2019)

WW = Week of the year

D = day of the week (ex: Sun=1, Mon=2, Tue=3, Wed=4, Thu=5, Fri=6, Sat=7)

Ezurio Part Number	Factory Effectivity – Date Codes
453-00139R	0925362
453-00139C	0925362
453-00139-K1	1025336
453-00140R	0925336
453-00140C	0925336
453-00140-K1	1025336

6.2 Inventory Management

Running change into production.

7 Contact Information

Headquarters Ezurio
50 S Main St., Suite 1100
Akron, OH 44308 USA
Tel: 1(330) 434-7929
Fax: 1(330) 434-7931

Website www.ezurio.com

Sales / Support Contact <https://www.ezurio.com/contact>

Product Change Notices (PCNs) will be distributed at the discretion Ezurio. Occasionally, Ezurio may adjust product revision levels for internal tracking purposes only, and customers may not receive formal notifications associated with those revision changes.