

# Release Notes

## BL5340 Vibration Demo Recorder Firmware (480-00120)

*Version 1.0.0 (GA1)*

*August 2021*

Release notes are a summary of new and enhanced features, resolved issues, and known issues that are not resolved in this firmware version. This release note describes the changes and enhancements to the 480-00120 Vibration Demo Recorder sample application for the BL5340 Bluetooth Low Energy Module in reverse chronological order.

For each version (excluding the initial 5.1.9) there are subsections for New Features, Bug Fixes, and Known Issues.

Ezurio Zephyr firmware version numbers consist of four numbers in the format **X.Y.Z**

**X** is used to indicate the major software version

**Y** is used to indicate the minor software version

**Z** is used to indicate the patch software version

- **Version 1.0.0 (GA1)**

## Version 1.0.0 (GA1)

*August 2021*

This firmware is built using the nRF Connect SDK version 1.6.1 using Zephyr 2.6 which is BT Spec version 5.0 qualified.

### Known Issues

There are no known issues with this release.

### Further Information

Further information relating to the BL5340 and its firmware is available from the Ezurio website at <https://www.ezurio.com/wireless-modules/bluetooth-modules/bluetooth-5-modules/bl5340-series-multi-core-bluetooth-52-802154-nfc-modules>