

Product Change Notification (PCN)

PCN #: 10A-2025

Date: October 28th, 2025

1 Products Affected

Ezurio Part Number	Revision Previous	Current Revision	Description
RG186 (450-0176)	13	14	Kit, Sentrius Gateway, 868 MHz internal part number 450-0176)
RG191 (450-0175)	11	12	Kit, Sentrius Gateway, 915 MHz (internal part number 450-0175)
455-00028	11	12	Kit, Sentrius RG186 Gateway, UK, 868MHz
455-00054	9	10	Kit, Sentrius RG191 Gateway, TW, 923MHz
455-00055	8	9	Kit, Sentrius RG191 Gateway, NZ, 923MHz
455-00056	8	9	Kit, Sentrius RG191 Gateway, HK, 923MHz
455-00057	8	9	Kit, Sentrius RG191 Gateway, AU, 902-928MHz
455-00102	7	8	Kit, Sentrius RG191 Gateway, SG, 923MHz
Included Sentrius Gateway	Associated Kit		
450-0174	13	14	Gateway, Sentrius, 868 MHz (used in 450-0176 & 455-00028)
450-0179	12	13	Gateway, Sentrius, 915 MHz (used in 450-0175)
450-00055	8	9	Gateway, Sentrius, 915 MHz (used in 455-00054)
450-00056	8	9	Gateway, Sentrius, 915 MHz (used in 455-00055)
450-00057	8	9	Gateway, Sentrius, 915 MHz (used in 455-00056)
450-00058	8	9	Gateway, Sentrius, 915 MHz (used in 455-00057)
450-00106	7	8	Gateway, Sentrius, 915 MHz (used in 455-00102)

These top-level orderable part numbers include various accessories and packaging, as well as the main Sentrius LoRa Gateway. All changes implemented in these kits have been associated with the LoRa Gateway itself, and the table “**Included Sentrius Gateway**” above shows the correlation between the included gateway and associated kits.

2 Description of Changes

The company name has been officially changed from Laird Connectivity to Ezurio. As a result, all product PCB Silkscreen labeling and packaging that previously displayed the Laird Connectivity logo will now feature the updated Ezurio logo. This change includes, but is not limited to:

- Product labels
- Product packaging

In addition, units will ship with **Firmware Release GA 8 – FW v12.178.0.18** and release notes located at the below link:

[GA8 FW Release Note v12.178.0.18](#)

3 Reason for Change

This change is being implemented because the company name has been officially changed from Laird Connectivity to Ezurio and to incorporate the major GA 8 FW update.

4 Anticipated Impact of the Change

Software Bug Fixes from Release Notes.

5 Method of Identifying the Changed Product

5.1 Top Level Part Number Changes (Packaged Kits)

Revision changes are available as a revision number printed on kit content label for all kits. The specific kit part number and revision are printed on the label within red square area, highlighted below.




5.1 Gateway / Assembly Changes

The labelling changes for all Gateways – revision changes are available as a revision number printed by barcode and within barcode for all gateway back labels.



5.2 Gateway Website GUI

The gateway's website GUI has been rebranded and color schemed to fit Ezurio.



6 Factory Effectivity Date

This will be a running change – New revision product should start shipping January 2026

7 Contact Information

Headquarters Ezurio
 50 S Main St., Suite 1100
 Akron, OH 44308 USA
 Tel: 1(330) 434-7929
 Fax: 1(330) 434-7931

Website www.ezurio.com

Sales / Support Contact <https://www.ezurio.com/contact>

Product Change Notices (PCNs) will be distributed at the discretion Ezurio. Occasionally, Ezurio may adjust product revision levels for internal tracking purposes only, and customers may not receive formal notifications associated with those revision changes.